



The Control Strip Results report displays the parameters being tracked, the deviation from the aim, an indication of process control status, e.g. out of action or out of control, and the densities from each step. Note that steps 8, 10 and 12 have red asterisks in the margin. Windense has automatically calculated the appropriate steps for LD, MD & HD.