



The Control Strip Results report gives the deviation from Reference and highlights parameters that are out of control or out of action in addition to raw densities for each step. In this case, the parameters tracked include DMax, DMin and various true speed and contrast parameters. Users can define parameters tracked and can use HD, MD & LD if desired.