

Windense - [02908:Deluxe 8095 Paper 01/10/05 11:17]


File Tools Windows Help

Control Strip Results

02908:Deluxe 8095 **000002908 Paper** **01/10/05** **11:17**

01/21/05

Process : RA-4
Reference : 3068 290810/06/0310:21
Machine : QSS-2611
Chemistry : Generic 3
Test : Production



Parameter	Red	Green	Blue	Spread
Black	-0.16	-0.32	-0.27	+0.16
Contrast	+0.01	-0.04	+0.02	+0.06
Speed	-0.04	+0.01	-0.07	+0.08
Stain	+0.00	-0.01	-0.01	+0.01

CFs are OK

Control status : **Out of Control Limits**

22

Inbox - Microsoft... Screen Shots - In... WindensePhoto... C:\Users\Bob\De... C:\PMA\HUB Windense - [0290... Document3 - Mi... 9:55 AM

The Control Strip Results report shows deviation from aim. Out of Action and Out of Control parameters are highlighted and so is overall process status (Out of Control Limits in this case.)